

9915DA-1x16-12G, 9915DA-2x16-XPT-12G Cobalt ROYAL, and 9915DA-4x16-XPT-12G Cobalt ROYAL

You can update your card by downloading the new Update software by going to the Support>Firmware link at www.cobaltdigital.com.

Download “Firmware Update Guide”, which provides simple instructions for downloading the latest firmware for your card onto your computer, and then downloading it to your card through DashBoard™.

Software updates are field-installed without any need to remove the card from its frame.

The table below lists released software versions and describes the corresponding functions additions, improvements, or corrections.

Firmware Version	Description
9915DA Firmware Release v3.2.3 (7/30/2025)	Bug Fix <ul style="list-style-type: none"> Addresses an issue where under certain conditions the device may not initialize in DashBoard.
9915DA Firmware Release v3.1.2 (3/12/2023 – 7/30/2025)	Bug Fix <ul style="list-style-type: none"> Inversion on outputs C and D, found when feeding the signal (C or D) to the 9992-ENC.
9915DA Firmware Release v3.1.1 (6/17/2022 – 3/12/2023)	Added Features <ul style="list-style-type: none"> Updated internal build systems. Bug Fix <ul style="list-style-type: none"> Configuration retains settings when the system powers cycles or reboots.
9915DA Firmware Release v2.5 (6/24/2021 – 6/17/2022)	Added Features <ul style="list-style-type: none"> (Option -DA-FSP only) new or expanded SFP status information on the SFP tabs/sub-tabs.
9915DA Firmware Release v2.3 (1/25/2021 – 6/24/2021)	Bug Fix <ul style="list-style-type: none"> Corrected card status display rows for inputs which may not be present on card model (for example, “Input C” and “Input D” status displayed rows for model 9915DA-2x16-XPT-12G which does not have these inputs).
9915DA Firmware Release v2.0 (1/29/2020 – 1/25/2021)	Bug Fix <ul style="list-style-type: none"> (Option -DA-FSP only). Where SFP1-A/SFP-1-B Out and SFP2-A/SFP-2-B Out UI columns were reversed. (Option -DA-FSP only). Where DashBoard may show Unlocked for SFP Rx ports, even though SFP Rx was indeed receiving and locking to input.
9915DA Firmware Release v1.5 and earlier	Non-official release (beta or other releases).